



Software Release Supplemental Document for Stone Peak/Wilkins Peak/Legacy Devices

WW05, 2015



Content Overview

How to get HW Chip stepping

LPM-L1 statement

BT Certification information

BT SW Version explanation

BT SW Update Recommendations

Installer information

BT logging information

Platform/OS Matrix

Chip Stepping Verification methods

SW releases since 17.13 include support for indicating the chip stepping


Two methods are available to determine the chip stepping.

1). A command line tool called `ibtver` is supplied with the trace tool. An example can be found below. The link to the trace tool can be found near the end of this document.

2). A hexadecimal version string is available in the UI. Please see the explanation below.

Method 1 - Chip Stepping info via Ibtver

Ibtver produces actual stepping and version string.




```
Administrator: Command Prompt
Volume in drive F is NEUROMANCER
Volume Serial Number is C49C-3FAD

Directory of F:\ibtttracetool_1_7_10
10/03/2014 02:59 PM <DIR>      .
10/03/2014 02:59 PM <DIR>      ..
10/03/2014 02:59 PM <DIR>      providers
10/03/2014 02:59 PM <DIR>      scripts
10/03/2014 02:59 PM <DIR>      tools
12/18/2013 10:17 PM           480 tracestart.cmd
12/18/2013 10:17 PM           314 tracestop.cmd
10/03/2014 11:52 AM           1,227 usage.txt
3 File(s)                2,021 bytes
5 Dir(s)                  619,124,543,488 bytes free

F:\ibtttracetool_1_7_10>cd tools
F:\ibtttracetool_1_7_10\tools>ibtver.exe
ibtusb.sys version: 17.1.1434.2
Product: Intel® Wireless Bluetooth® 7265 Rev. C0
FW Version: 37 08 10 01 10 02 27 0d 1a
F:\ibtttracetool_1_7_10\tools>
```

Invoke ibtver from the trace tool to get the chip stepping

Method 2 - Chip Stepping info via UI



Translation Table for UI Version String (method 2)

ibtvver Output	Module & Stepping
37 07 10 01 80 02 03 0d XX	7260 B3
37 07 10 01 00 02 03 0d XX	3160 B4
37 07 10 01 80 01 2d 0d XX	7260 B5
37 07 10 01 00 01 2d 0d XX	3160 B6
37 08 10 01 10 02 27 0d XX	7265 C0
37 08 10 01 10 03 11 0e XX	7265 D0

W – Wilkins Peak

S – StonePeak

XX - Patch version, ignored

Note 1. Explanation about LPM-L1

An intermittent problem was discovered during a file transfer test on Win7. When the problem occurs the file transfer can fail.

After further examination Intel has decided that enabling LPM-L1 introduced unwarranted risk and so LPM-L1 support will not be indicated from the device across all OS's until further notice.

StP BT Certification Info

OS	Declaration ID Controller
Win 7	D021279
Win 8.X	D021279

Explanation about BT SW Versions

On Stone Peak Motorola BT Stack Profiles can be used with Win7. Intel provides driver SW which Motorola packages up with it's SW.

This is why there are 3 versions displayed in Device Manager and Programs and Features. The Intel, Motorola driver and Motorola package versions are displayed.

Program's and Features shows the Intel Driver and the Motorola SW Package version on the same line.

Device Manager shows the Motorola Driver contained within the Motorola SW Package. Sometimes the Motorola SW Package version number and the Motorola match. When they do not match it means the Motorola Driver did not change but the Intel SW did and the so the Motorola Package Version incremented.

Version Numbers in DM and Program's and Features (example)

The screenshot displays two windows from a Windows 7 desktop. The left window is 'Computer Management' showing the 'Intel(R) Wireless Bluetooth(R) Properties' dialog box. The 'Driver Date' is 6/17/2014 and the 'Driver Version' is 17.1.1407.074, which is highlighted with a red box and labeled 'Motorola Driver'. The right window is 'Control Panel > All Control Panel Items > Programs and Features'. It shows a list of installed programs with columns for Name, Publisher, Install Date, Size, and Version. The entry 'Intel(R) Wireless Bluetooth(R) (patch version 17.1.1434.2)' is highlighted with a red box, showing a size of 53.2 MB and a version of 17.1.1407.0480, which is labeled 'Motorola Package Version'. Below the table, it states 'Currently installed programs Total size: 250 MB' and '9 programs installed'.

Name	Publisher	Install...	Size	Version
PUTTY version 0.63	Simon Tatham	9/9/2014	3.48 MB	0.63
Microsoft Visual C++ 2010 x86 Redistributable - 10.0.30319	Microsoft Corporation	9/12/2014	11.0 MB	10.0.30319
Microsoft Visual C++ 2010 x64 Redistributable - 10.0.30319	Microsoft Corporation	9/12/2014	13.1 MB	10.0.30319
Microsoft .NET Framework 4 Extended	Microsoft Corporation	9/12/2014	51.9 MB	4.0.30319
Microsoft .NET Framework 4 Client Profile	Microsoft Corporation	9/12/2014	38.8 MB	4.0.30319
Intel PROSet/ Wireless Software	Intel Corporation	9/12/2014	249 KB	17.0.3
Intel Graphics Driver	Intel Corporation	9/12/2014	74.2 MB	10.18.10.3621
Intel(R) Wireless Bluetooth(R) (patch version 17.1.1434.2)	Intel Corporation	9/12/2014	53.2 MB	17.1.1407.0480
7-zip 9.2.0 (x64 edition)	Igor Pavlov	9/12/2014	4.53 MB	9.20.00.0

Windows Update for 8.1

KB2896349

KB2917488

2927446

2928042

2919907

2926971

Intel strongly recommends customers perform a WU in order to get these important KBs from MS. These are BT related fixes.

BIOS Update

- Intel recommends that OEMs update their platform BIOS to the latest version. Some issues that were reported as BT issues resulted in a change in the BIOS

- Relevant fix:

LYNX_POINT_LP [HSD #2164696][XHCI: Resume EOP from host seen after a large delay]

KIT#: 100999

Intel® 8 Series / C220 Series Chipset Family and Lynx
Production Version 1.8.0

Point- LP PCH Chipset Framework Reference Code

Microsoft Errata(For Your Information)

Errata 3102:

Title:

Windows 8.1 systems that have WiFi but doesn't have Bluetooth.

After setup the environment for test on HCK, we found that Bluetooth related items are appearing.

Details:

Delayed Enforcement of Bluetooth in Systems (Except for Tablet or Convertible Product Type)

Expires:

1/1/2015

Requirement: System.Client.BluetoothController.Base.BluetoothRequiredIfWiFiPresent

Supported OS:

Windows 8 x86/x64; Windows 8.1 RT; Windows 8.1 x86/x64; Windows RT

Microsoft Errata – cont.

Errata 3355:

Title:

BT System WHCK - Enable BT Radio fails on executing 'System - Radio On-Off Logo Tests (Windows v6.3)'

Details:

Test Failures in Bluetooth LE Logo Tests and Radio On Off tests when testing on the Intel/Broadcom Platform

Seeing an issue where BT radio is not getting enabled while executing 'System - Radio On-Off Logo Tests (Windows v6.3)' test. This happens with Win8.1 BT Inbox driver also.

This applies to both the System and Device HCK programs. OEMs using the Broadcom UART based radios may run into test failures in either Bluetooth LE or Radio On Off Bluetooth logo tests.

Expires:

12/31/2014

For any questions/help in applying this errata, please contact the Microsoft feature team.

Microsoft KB

Issue:

Windows 8.1\BT stack not sending reset to controller before S3 leaving device power on.

- Microsoft case ID: REG:114011011081840
- KB from Microsoft: <http://support.microsoft.com/kb/2887179>

Installer Options

- To install USB only patch drivers (without RF Kill support) `msiexec /i "Intel Bluetooth.msi" /q AddLocal=USB Remove=RFKILL`

(Note: 'Remove=RFKILL' Option was developed for customers who rely on HW RF Kill)

- To install all the components (patch drivers and RF Kill support)

`msiexec /i "Intel Bluetooth.msi" /q AddLocal=USB,RFKILL`

- To uninstall the existing installation (this will uninstall all features)

`msiexec /x "Intel Bluetooth.msi" /q`

Don't uninstall via the device manager.

Installer Options (cont.)

- SUPPORTREMOTEWAKEUP=TRUE/FALSE

This property when set to TRUE, will add the registry keys that will enable the remote device wakeup.

The default value is FALSE and so these keys are not added.

- Example: To install only the patch driver (without RF Kill support) and to add the registry keys for remote wakeup support

```
msiexec /i "Intel Bluetooth.msi" /q AddLocal=USB Remove=RFKILL SUPPORTREMOTEWAKEUP=TRUE
```

TIC Installation instructions

Verify that a supported Bluetooth NIC is installed on-board.
Install Motorola Bluetooth Profile Pack by running "Autorun" and follow graphical wizard instructions.

Installation commands:

Command name and possible values

LPUSBHUBWA=TRUE

LPUSBHUBWA=FALSE

PAGESCANMGMT=FALSE

PAGESCANMGMT=TRUE

Legal Disclaimer

INFORMATION IN THIS DOCUMENT IS PROVIDED IN CONNECTION WITH INTEL PRODUCTS. NO LICENSE, EXPRESS OR IMPLIED, BY ESTOPPEL OR OTHERWISE, TO ANY INTELLECTUAL PROPERTY RIGHTS IS GRANTED BY THIS DOCUMENT. EXCEPT AS PROVIDED IN INTEL'S TERMS AND CONDITIONS OF SALE FOR SUCH PRODUCTS, INTEL ASSUMES NO LIABILITY WHATSOEVER AND INTEL DISCLAIMS ANY EXPRESS OR IMPLIED WARRANTY, RELATING TO SALE AND/OR USE OF INTEL PRODUCTS INCLUDING LIABILITY OR WARRANTIES RELATING TO FITNESS FOR A PARTICULAR PURPOSE, MERCHANTABILITY, OR INFRINGEMENT OF ANY PATENT, COPYRIGHT OR OTHER INTELLECTUAL PROPERTY RIGHT.

All products, dates, and figures specified are preliminary based on current expectations, and subject to change w/o notice. Intel may make changes to specifications and product descriptions at any time, without notice.

Intel, processors, chipsets, and desktop boards may contain design defects or errors known as errata, which may cause the product to deviate from published specifications. Current characterized errata are available on request.

Any code names featured are used internally within Intel to identify products that are in development and not yet publicly announced for release. Customers, licensees and other third parties are not authorized by Intel to use code names in advertising, promotion or marketing of any product or services and any such use of Intel's internal code names is at the sole risk of the user.

Intel product plans in this presentation do not constitute Intel plan of record product roadmaps. Please contact your Intel representative to obtain Intel's current plan of record product roadmaps.

Software and workloads used in performance tests may have been optimized for performance only on Intel microprocessors. Performance tests, such as SYSmark and MobileMark, are measured using specific computer systems, components, software, operations and functions. Any change to any of those factors may cause the results to vary. You should consult other information and performance tests to assist you in fully evaluating your contemplated purchases, including the performance of that product when combined with other products. For more information go to www.intel.com/performance

Results have been estimated based on internal Intel analysis and are provided for informational purposes only. Any difference in system hardware or software design or configuration may affect actual performance.

Intel does not control or audit the design or implementation of third party benchmark data or Web sites referenced in this document. Intel encourages all of its customers to visit the referenced Web sites or others where similar performance benchmark data are reported and confirm whether the referenced benchmark data are accurate and reflect performance of systems available for purchase.

References to 802.11n and 802.11ac performance are based on theoretical bandwidth maximums enabled by various 802.11n and 802.11ac specifications. Actual throughput will vary on your specific device operating system, hardware, software configurations, Internet connection speed and environmental conditions.

Intel® Wireless Display requires an Intel® Wireless Display enabled PC, tablet, or smartphone, a compatible adapter, and a TV. 1080p and Blu-Ray* or other protected content playback only available on select Intel® processors with built-in visuals enabled. Consult your PC manufacturer. For more information, see www.intel.com/go/widi

Intel® vPro™ Technology is sophisticated and requires setup and activation. Availability of features and results will depend upon the setup and configuration of your hardware, software and IT environment. To learn more visit: <http://www.intel.com/technology/vpro>

Intel® Active Management Technology requires activation and a system with a corporate network connection, an Intel® AMT-enabled chipset, network hardware and software. For notebooks, Intel® AMT may be unavailable or limited over a host OS-based VPN, when connecting wirelessly, on battery power, sleeping, hibernating or powered off. Results dependent upon hardware, setup and configuration. For more information, visit [Intel® Active Management Technology](#).

Intel Dual Band Wireless-AC 8260, Intel Dual Band Wireless-AC 3165, Intel Dual Band Wireless-AC 7265, Intel Dual Band Wireless-N 7265, Intel Wireless-N 7265, Intel Dual Band Wireless-AC 7260, Intel Dual Band Wireless-N 7260, Intel Wireless-N 7260, Intel Dual Band Wireless-AC 3160, Intel Smart Connect Technology, Intel Wireless Display, Intel vPro Technology, Intel Active Management Technology, Intel PROSet/Wireless Software, Intel PROSet/Wireless Software for Bluetooth Technology, Location Based Service, Intel Remote Wake Technology, Intel, Intel Inside, the Intel logo, Intel Core, Intel, Intel logo are trademarks of Intel Corporation in the United States and other countries.

This document contains information on products in the design phase of development.

*Other names and brands may be claimed as the property of others.

Copyright © 2015 Intel Corporation, All Rights Reserved

